

Menu

HISTORY FILE MAP for year 2007

REALTIME

PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK

275.03:26-03:35 9m realtime 1024 bps lost due to DSS-24 late in locking onto 1024 bps. DR G108076 refers.

278.22:10-22:26 16m realtime 1024 bps lost due to DSS-54 inability to lock onto 1024 bps telemetry. Telemetry restored following switch over to new downlink control channel. DR M104447 refers.

